

Part-1

Performa For The Safety School Building
(To be filled by the Head of School/Institute)

1 Name of School S.A.N Jain Model Sen. Sec. School
 2 Location Circular Road, Ludhiana
 3 Plot Area 3.51 Acres (16988.40) Sq. Yd.
 4 Plinth Area 83383.60 Sq. Ft.
 5 Number of Storey Teipple
 6 Year of Construction of building Main Block - 1966 to 1970
 7 supervision of the qualified Engineer, Primary Block - 1972 to 1980
Nursery Block - 1991

The Following details may be given:

- a) Name of Engineer
- b) Address
- c) Set of Structure Drawing used in the construction if available
- d) Name of the Architect Modern Architects & Associates

8 Whether the building has been constructed for the Purpose of :

- a) School (Yes/No) Yes
- b) Residential purpose and converted for use as a school (Yes/No) No

9 Materials used of Roof:

- a) R.C.C slabs (Yes/No) Yes
- b) R.S joists and Battents (Yes/No) No
- c) Wooden Joists and Battents (Yes/No) No

10 Materials used of wall:

- a) Mud Mortar (Yes/No) No
- b) Cement Mortar (Yes/No) Yes
- c) Plaster (i) Lime mortar (Yes/No) No
 (ii) Cement Mortar (Yes/No) Yes

11 Flooring :

- a) Conglomerate (Yes/No) Yes
- b) Terrazzo (Yes/No) No
- c) Brick Paving (Yes/No) Yes

12 Detailed Drawing indicating dimensions of the rooms along with size and location of doors and windows Building maps are attached along with this performa.

Signature with stamp of
The Head of the school / institute

Meena Jain
 Mrs. Meena Jain (Principal)
 S.A.N Jain Model Sen. Sec. School
 Circular Road, Ludhiana.
 Affiliation No-LS-4374

Part-II

(To be filled by S.D.E. for P.W.D. B&R Department)

I have visited the above mentioned school on 12/9/2022 and have visually inspected it from all angles of safety and I found it fit for normal use as school building.

In case any addition/ alteration of expansion and modification of this building is to be carried out the same be carried out under the supervision of a technically specified Engineer and this certificate may again be obtained after the completion of work from the undersigned.

In case the building is affected by flood or if there is settlement of walls/ foundations or caves of roof etc. immediately inspection of the undersigned be arranged to check the stability and safety of the building.

This building can be safely occupied for normal use up to 31/3/2023 (indicate year up to which it can be used).

(पिती: ~~सुनील~~ सिंह गरोडा)
रूप मंडल इंजीनियर
पुं रूप मंडल नं. 3,
ल.न.वि. ड डे म साधा, लुधियाना।

817
12/9/2022